

Section V - Reactivity Data		RUGGEDCUT LIGHT CUTTING AND THREADING OIL		RL
Stability:	Unstable:		Conditions to Avoid: NONE	
	Stable:	X		
Incompatibility (Materials to Avoid): .				
Hazardous Decomposition or Byproducts:				
Hazardous Polymerization:	May Occur:		Conditions to Avoid: NONE	
	Will Not Occur:	X		
Section VI - Health Hazard Data				
Route(s) of Entry:	Inhalation? NO	Skin? NO	Ingestion? NO	
Health Hazards (Acute and Chronic): NONE KNOWN				
Carcinogenicity:	NTP? NO	IARC Monographs? NO	OSHA Regulated? NO	
Signs and Symptoms of Exposure: EYES: IRRITATION OR REDNESS OF EYES.				
Medical Conditions Generally Aggravated by Exposure: NONE KNOWN				
Emergency and First Aid Procedures: EYES: AS WITH MOST FOREIGN MATERIALS, SHOULD EYE CONTACT OCCUR, FLUSH EYES WITH PLENTY OF WATER.				
Section VII - Precautions for Safe Handling and Use				
Steps to Be Taken in Case Material is Released or Spilled: WIPE UP OR ABSORB ON SUITABLE MATERIAL AND SHOVEL UP.				
Waste Disposal Method: DOES NOT MEET CRITERIA OF A HAZARDOUS WASTE. DISPOSE OF ACCORDING TO LOCAL, STATE, AND FEDERAL REGULATIONS.				
Precautions to Be Taken in Handling and Storing: MINIMUM FEASIBLE HANDLING TEMPERATURES SHOULD BE MAINTAINED. PERIODS OF EXPOSURE TO HIGH HEAT SHOULD BE MINIMIZED. WATER CONTAMINATION SHOULD BE AVOIDED.				
Other Precautions: N/A				
Section VIII - Control Measures				
Respiratory Protection (Specify Type): N/A				
Ventilation:	Local Exhaust: NORMAL VENTILATION		Special: N/A	
	Mechanical (General): N/A		Other: N/A	
Protective Gloves: N/A		Eye Protection: CHEMICAL TYPE GOGGLES OR FACE SHIELD OPTIONAL		
Other Protective Clothing or Equipment: NORMAL WORK CLOTHES				
Work/Hygienic Practices: EXERCISE REASONABLE PERSONAL CLEANLINESS				