

# GLUE-WASH

## PUMICE HAND CLEANER

### USAGE:

**GLUE-WASH** safely cleans all ABS, PVC and CPVC Plastic Solvent Cements from hands. Also removes Foam Sealants, Silicone, Epoxy, Dry Paint\* and more.

**TEMPERATURE RANGE USE:**  
25°F (-4°C) to  
120°F (49°C)

**COLOR/  
CONSISTENCY:**  
Gray Lotion

### AVAILABLE SIZES:

Stock #	Size
GWP4	4 fl. oz (118 ml)
GWP16	16 fl. oz (473 ml)

\*Avoid contact with painted surfaces.




- **Safely Removes ABS, PVC and CPVC Plastic Solvent Cements from Hands**

- **Removes Paint, Foam Sealants, Silicones, and more**

- **Biodegradable and Safe for Skin**

- **Great for Everyday Use**

- **Contains Pumice Scrubbers and Lanolin to Protect Skin**



### Directions for Use:

1. Shake **GLUE-WASH** well before using.
2. Apply lotion onto harden cement, paint or dye. Work into hands for 30 to 40 seconds to loosen.
3. Wipe with dry rag or rinse with water.

**Distributed By:**



**MADE IN U.S.A.**

**W WHITLAM**

J.C. Whitlam Manufacturing Co.  
P.O. Box 380 • Wadsworth, OH 44282  
U.S. & Canada

Phone: 800-321-8358  
FAX: 800-537-0588

International  
Phone: 330-334-2524  
FAX: 330-334-3005



[www.gluewash.com](http://www.gluewash.com)

© 2021 J.C. Whitlam Manufacturing Co.